

READ ME

Inverter	SB 3000TL-21 SB 3600TL-21 SB 4000TL-21 SB 5000TL-21 SB 6000TL-21
FW-Version	PACK 2.81.01 (HP 2.53)
Update feature/reason	<ul style="list-style-type: none"> • New country settings: AS4777.2:2015 (rotary switch position 2A) • Improve SunSpec-Profil register Improved CEI 0-21 Selftest
Update medium	<ul style="list-style-type: none"> • Sunny Explorer (from version 1.07.11) • Sunny WebBox with Bluetooth® Wireless Technology
File-Name	FW2.81.01_SB3-6000TL-21_Sunny_Explorer_or_WebBox_with_BT.zip
Update manual	Sunny Explorer: Please go to the SMA download area and do as follows: https://www.sma.de/service/downloads.html Search for "Explorer-BA" and select your preferred language.
	Sunny WebBox (as from FW-Version 1.53/Profile Version 1.43): Please go to the SMA download area and do as follows: https://www.sma.de/service/downloads.html Search for "SWebBox-BA" and select your preferred language.
	Sunny WebBox with Bluetooth® Wireless Technology: Please go to the SMA download area and do as follows: https://www.sma.de/service/downloads.html Search for "SWebBox20" and select your preferred language.
	SMA Cluster Controller: Please go to the SMA download area and do as follows: https://www.sma.de/service/downloads.html Search for "ClusterController-BA" and select your preferred language.
Note	<ul style="list-style-type: none"> • The update file contains all features of former firmware version <ul style="list-style-type: none"> - New country settings: AS4777.2:2015 (rotary switch position 2A) - Improve SunSpec-Profil register