

READ ME

Inverter	SB 3000TL-21 SB 3600TL-21 SB 4000TL-21 SB 5000TL-21 SB 6000TL-21	
FW-Version	PACK 2.81.01 (HP 2.53)	
Update feature/reason	<ul style="list-style-type: none"> New country settings: AS4777.2:2015 (rotary switch position 2A) Improve SunSpec-Profil register Improved CEI 0-21 Selftest 	
Update medium	SD card (directly on the inverter)	
File-Name	FW2.81.01_SB3-6000TL-21_SD-Card.zip	
Update manual (link)	EN	http://files.sma.de/dl/1348/NG_UpdSD-TB-en-32.pdf
	DE	http://files.sma.de/dl/1348/NG_UpdSD-TB-de-32.pdf
	FR	http://files.sma.de/dl/1348/NG_UpdSD-TB-fr-32.pdf
	ES	http://files.sma.de/dl/1348/NG_UpdSD-TB-es-32.pdf
	GR	http://files.sma.de/dl/1348/NG_UpdSD-TB-el-32.pdf
	IT	http://files.sma.de/dl/1348/NG_UpdSD-TB-it-32.pdf
	KR	http://files.sma.de/dl/1348/NG_UpdSD-TB-ko-32.pdf
	NL	http://files.sma.de/dl/1348/NG_UpdSD-TB-nl-32.pdf
	PT	http://files.sma.de/dl/1348/NG_UpdSD-TB-pt-32.pdf
	If the download link doesn't work, please go to the SMA download area and do as follows: https://www.sma.de/service/downloads.html Search for "NG_UpdSD-TB" and select your preferred language.	
Note	<ul style="list-style-type: none"> New country settings: AS4777.2:2015 (rotary switch position 2A) Improve SunSpec-Profil register Improved CEI 0-21 Selftest <p>The package includes 2 update files (*.up2 and *.bin). Both files need to be copied to the SD card.</p>	