

READ ME

Inverter	SB 2000HF-30 SB 2500HF-30 SB 3000HF-30	
FW-Version	Package 2.54.11.R	
Update feature/reason	<p>This firmware package is only required for replacing the display from model LCD-11 to LCD-12 in case of service or repair</p> <p>The package does not contain new functionality compared to package version 2.54.07.R</p> <p>The inverter need to be updated <u>before</u> the display is replaced</p>	
Update medium	SD card (directly on the inverter)	
File-Name	FW2.54.11.R_SB2000-3000HF_SD-Card.zip	
Update manual (link)	EN	http://files.sma.de/dl/1348/NG_UpdSD-TB-en-32.pdf
	DE	http://files.sma.de/dl/1348/NG_UpdSD-TB-de-32.pdf
	FR	http://files.sma.de/dl/1348/NG_UpdSD-TB-fr-32.pdf
	ES	http://files.sma.de/dl/1348/NG_UpdSD-TB-es-32.pdf
	GR	http://files.sma.de/dl/1348/NG_UpdSD-TB-el-32.pdf
	IT	http://files.sma.de/dl/1348/NG_UpdSD-TB-it-32.pdf
	KR	http://files.sma.de/dl/1348/NG_UpdSD-TB-ko-32.pdf
	NL	http://files.sma.de/dl/1348/NG_UpdSD-TB-nl-32.pdf
	PT	http://files.sma.de/dl/1348/NG_UpdSD-TB-pt-32.pdf
	<p>If the download link doesn't work, please go to the SMA download area and do as follows: https://www.sma.de/service/downloads.html Search for "NG_UpdSD-TB" and select your preferred language.</p>	
Notes	The package contains two update files which need to be located in the identical directory of the SD card	